



Bulletin No: SB2003-07

Category: STEINER

Section:

Index Ref: N/A

Machine/s: ZTM 200

Pages: 1

Date: October 2003

Type: Product Information

TO: All Steiner Dealers

SUBJECT: Transmission Maintenance

ISSUE:

Correction to manual 4125719 and 4125719 Rev. A. **We DO NOT require you to change the transmission hydraulic oil after 5 hours of use as stated in the Maintenance Record section of the manual.**

CORRECTION:

On the page labeled Maintenance Record of the Steiner Operation, Safety and Maintenance Manual, you need to change the NOTE on the bottom of the page to read as follows: **After first 5 hours of operation replace engine oil and filter.** This is for ZTM 200 model only.

AFFECTED SERIAL NUMBERS:

All serial numbers for the following models:
442280, 442281, 442282

WARRANTY:

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Johnson Creek product support team at 1-800-848-1636 option 2,2.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☐ PARTS ☒

