



Bulletin No: SB2004-02
Category: STEINER
Section:
Index Ref: N/A
Machine/s: UM428
Pages: 1
Date: June 21, 2004

Type: Action Required

TO: Steiner Dealers
SUBJECT: Steering Cylinder Mount

ISSUE:
Replacement of the steer cylinder mount.

CORRECTION:
We will be sending one kit 970310 per unit, to the selling dealer. Kit needs to be installed before December 21st, 2004 on the provided serial numbered units.

AFFECTED SERIAL NUMBERS:
All serial numbers for the following models:

75-70132	Serial numbers	W1201 up to and including W1300
75-70134	Serial numbers	X1282 up to and including X1335
75-70134	Serial number	75701340070
75-70136	Serial numbers	Y1311 up to and including Y1341

WARRANTY:
Please file warranty claims, using **Factory Approval Number SB2004-02**. You may claim up to one-hour labor for repair.
Retailed units registered will be eligible for \$50.00 administration/pick and delivery charge.

If you have any questions please contact Jacobsen Service Department @ 800-848-1636 select option 3,2.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE WARRANTY SALES PARTS

