





Bulletin No: SB2004-12 Category: STEINER Section: N/A

Index Ref: N/A

Machine/s: Model 230

Pages: 1

Date: November 1, 2004

Type: Product Information

TO: All Steiner Dealers

SUBJECT: Kubota Diesel Exhaust

ISSUE:

We have changed the way the exhaust bellow is mounted on the 230 Kubota diesel.

CORRECTION:

When ordering the bellowed exhaust pipe, part number 13-093 you will need to order part number 4133607.7 exhaust bracket pipe and 4133640.7 R.H. side panel as the replacement.

AFFECTED SERIAL NUMBERS:

All serial numbers for the following models: Model 75-0265 serial numbers prior to 75702650136

WARRANTY:

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Jacobsen Product Support Team at 1-800-848-1636 option 3,2.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below.					Please circulate as appropriate			
SERVICE	X	WARRANTY	X	SALES	P/	ARTS	X	