



Bulletin No: SB2004-13
Category: STEINER
Section: N/A
Index Ref: N/A
Machine/s: Model 415
Pages: 1
Date: November 1, 2004

Type: Product Information

TO: All Steiner Dealers

SUBJECT: Kohler Muffler

ISSUE:

Muffler replacement on Kohler engine models.

CORRECTION:

When replacing muffler part number 13-071 you will get muffler part number 4132729. You will then need to remove heat shield, as it is no longer needed.

AFFECTED SERIAL NUMBERS:

All serial numbers for the following models:

Model 75-60010 serial numbers prior to 75600100228

WARRANTY:

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Jacobsen Product Support Team at 1-800-848-1636 option 3,2.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE	<input checked="checked" type="checkbox"/>	WARRANTY	<input checked="checked" type="checkbox"/>	SALES	<input type="checkbox"/>	PARTS	<input checked="checked" type="checkbox"/>
---------	--	----------	--	-------	--------------------------	-------	--