

Bunton

Product Type: BZT-31LCG Ref. No. 004 Service Bulletin J524

February 2001

Anti-Scalp Rollers

Models Affected: BZT-31LCG

<u>Issue</u>

We have changed the Anti-Scalp Rollers to a new ball design to help prevent tearing of the turf while turning.

Correction

When ordering a 3970242 Anti-Scalp Roller you will receive a **2721512** Anti-Scalp Roller. You will have to order a new mounting bolt **64123-152** 5/8"-11 X 5".

Effective Serial Number

All BZT-31I CG units.

Warranty

This bulletin is for informational purposes only. Warranty does not apply.

Parts Involved

3970242 Anti-Scalp Roller. 2721512 Anti-Scalp Roller. 3970197 Bolt. 64123-152 Bolt.

If you have any questions about this bulletin, please contact the Textron Golf, Turf And Specialty Products Service Department at 920-699-5890.