

Product Type: BZT2000

Bunton

Service Bulletin J550

July 2001

970235 Caster Wheel Anti-Shimmy Kit

Ref. No. 019

Models Affected: All BZT2000 with Ball Bearing Style Casters.

<u>Issue</u>

We have released an Anti - Shimmy Kit **970235** for the BZT2000 with Ball Bearing Style Casters.

Correction

If you are experiencing caster wheel wobbling on older style BZT2000 please order and install the above mentioned kit.

Effective Serial Number

All 642XXX units with Ball Bearing Style Casters.

Warranty

You may claim parts and up to 1 hour labor for units within the normal warranty period. Units outside the normal warranty period you may claim for parts only.

Parts Involved

970235 Kit - Caster Wheel Anti - Shimmy

2186123 Yoke

2720545 Yoke

2720618 48" LH Support

2720616 48" RH Support

2186175 52" LH Support

2186176 52" RH Support

2186173 61" LH Support

2186174 61" RH Support

2186177 60" LH Support

2186178 60" RH Support

If you have any questions about this bulletin, please contact the Textron Golf, Turf And Specialty Products Service Department at 920-699-5890.