





Bulletin No: SB2005-01 Category: Steiner Section: N/A

Index Ref: N/A

Machine/s: Miscellaneous

Pages: 2

Date: January 4, 2005

Type: Product Information

TO: All Steiner Dealers

SUBJECT:

### **ISSUE:**

In order to check your bulletin files, attached is a listing of bulletins released in 2004.

# **CORRECTION:**

Bulletins are listed by number. Copies of these bulletins are available on the Jacobsen web site under the dealer secure area.

## **AFFECTED SERIAL NUMBERS:**

None

#### **WARRANTY:**

This bulletin is for information purposes only.

# **CustomerOne™ Product Support**

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE

X

WARRANTY

 $\mathbf{X}$ 

**SALES** 

X

**PARTS** 

X

TYPE	#	YEAR	PRODUCT TYPE	TITLE	ISSUE	Part Number Involved
SB	1	2004	ZTM	Remote Engine Air Filter	Intake elbow may be warped - Attached is Kawaski Bulletin	See Bulletin
SB	2	2004	UM428	Steering Cylinder Mount	Mandatory Reploacement of Steering Cylinder Mount	970310
SB	3	2004	ZTM 200	Traction Control Lever	Improved Traction Control Lever	970314
SB	4	2004	General	38665 Soleniod	Proper Test Procedures	38665
SB	5	2004	ZTM Plus	Crankshaft Spacing	Proper Spacing Between Pulley and Electric Clutch	64163-44
SB	8	2004	Model 230	Drive Axle Kit	New Part Number for Drive Axle Kit	970311
SB	9	2004	Model 230	Drive Shaft	Improvements to Drive Shaft Assembly	4131504
SB	10	2004	Model 230	Drive Axle Seal	Add Axle Seal Behind Bearing to Prevent Oil Leak	4134039
SB	11	2004	Model 230	Kolher Muffler	Kit Needed When Replacing Muffler	970321
SB	12	2004	Model 230	Kubota Diesel Exhaust	Additional Parts Needed When Changing Exhaust Pipe	See Bulletin
SB	13	2004	Model 415	Kolher Muffler	Change to Muffler Part Number	4132729
SB	14	2004	Model 430	Kolher Muffler	Changes to Muffler and Mounting	See Bulletin
SB	15	2004	Model 230	Front Lift	Front Lift Latch Will Not Engage	62-539.7
SB	16	2004	Model 230	Linamar to Kolher Engine Conversion	Kit Available to Convert Linamar Engine to Kolher Engine	970318
SB	17	2004	ZTM200RS Plus	Transaxle Maintenance	Proper Maintenance Procedures	See Bulletin
SB	20	2004	ZTM	Hydraulic Testing	Proper Hydraulic Testing of Pumps and Wheel Motors	See Bulletin