



Ryan Information Bulletin

Product Type: Lawnaire IV & V

Ref. No. N/A

Bulletin No: C-018-05

April 11, 2005

Drive Belt Disengagement

Product Information

ISSUE:

In order to enhance our product, a torsion spring has been released to add additional disengagement of the drive wheel.

CORRECTION:

Install torsion spring part number **4137227** as shown.

PARTS INVOLVED:

4137227 Torsion spring
2703341.7 Idler Bell-crank

INVOLVED PRODUCTS:

544908A, 544909A, 544910A, 544911A, 544917



WARRANTY:

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Jacobsen Product Support Team at 1-800-848-1636 option 2,2.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☒ PARTS ☒

