



Product Type: BZT2000

Ref. No. 009

Bunt on

Service Bulletin J480

July 2000

Fuel Line Installation

Models Affected:
All BZT2000

Issue

We have found that the Fuel Line on some BZT2000's may not be properly installed.

Correction

Remove the Fuel Line Clamp and slide the Fuel Line completely onto the Suction Fitting, then reinstall the clamp.

Effective Serial Number

All BZT2000's.

Warranty

You may claim up to 15 minutes labor for machines within the normal warranty period. Please file warranty in the normal manner with one machine per claim.

Parts Involved

None.

If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty Products Service Department at 920-699-5890.