



Bulletin No: SB2005-09
Category: Steiner
Section: N/A
Index Ref: N/A
Machine/s: Model 415
Pages: 1
Date: June 20, 2005

Type: Product Information

TO: All Steiner Dealers

SUBJECT: Model 415 headlight kit

ISSUE:

We have received reports of headlights not staying in the front grill.

CORRECTION:

We have issued a kit part number 970322 that will prevent this from reoccurring.

AFFECTED SERIAL NUMBERS:

Model number 75-60010 serial numbers prior to 75600100306

WARRANTY:

You may claim kit and up to 0.50 hours labor for units within the warranty period that are experiencing this issue. Please file warranty using **Factory Approval Number SB2005-09** with one unit per claim. If you have any questions please contact the Johnson Creek Product Support Team at 1-800-848-1636 option 3,2.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☒ PARTS ☒

