



# Ryan Information Bulletin

**Product Type: Jr. Sodcutter**

**Ref. No. N/A**

**Bulletin No: C-039-05**

**August 8, 2005**

## Rear Wheel Spacer


### Product Information

#### ISSUE:

Rear Wheel not being held in place, allowing the bearing to be damaged.

#### CORRECTION:

Install 1 –2 spacers part number 64163-67 per side as shown in drawing, to shim rear wheel to forks within a 1/8" of play. Try to center wheel in between forks as much as possible.



Add here

#### PARTS INVOLVED:

64163-67

#### INVOLVED PRODUCTS:

544944A

544844D

544945A

544845D

#### WARRANTY:

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Jacobsen Product Support Team at 1-800-848-1636 option 2,3,1.

## CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☒ PARTS ☒

