



# Bobcat/Bunton Service Bulletin

**Product Type: Mid-Size**

**Ref. No. N/A**

**Bulletin No: C-034-05**

**August 8, 2005**

## Throttle Cable

### Action Required

#### ISSUE:

We have received reports of the throttle cable coming in contact with the muffler and melting the plastic coating.

#### CORRECTION:

When replacing throttle cable part number 38357-04 you will need to replace it with part number **38357-09** on the listed models below.

#### PARTS INVOLVED:

38357-04

38357-09

#### INVOLVED PRODUCTS:

633010A, 634010A, 930022A, 930023A, 930323A, 930325A, 930328A, 932010A, 933010A and 934010A

#### WARRANTY:

You may claim up to 0.2 hours of labor and parts for units covered under this bulletin. Please file warranty using Service Bulletin Number **C-034-05** with one unit per claim. If you have any questions please contact the Jacobsen Product Support Team @ 800-848-1636 option 2,3,1.

## CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☒ PARTS ☒

