



Bobcat/Bunton Information Bulletin

Product Type: Mid-Size

Ref. No. N/A

Bulletin No: C-033-05

August 8, 2005

Idler Pulley

Product Information

ISSUE:

We have received reports that the bearing in the Idler pulley is not lasting.

CORRECTION:

When replacing 48393 pulley-v idler on the listed models order part number **4135265** pulley-idler in its place.

PARTS INVOLVED:

48393

4135265

INVOLVED PRODUCTS:

633010A, 633405A, 633406A, 932010A, 933010A, 933405A, 933406A and 933407A

WARRANTY:

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Jacobsen Product Support Team at 1-800-848-1636 option 2,3,1.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE

☒

WARRANTY

☒

SALES

☒

PARTS

☒