



# Bobcat/Bunton Service Bulletin

Product Type: Miscellaneous

Ref. No. N/A

Bulletin No: C-045-05

November 28, 2005

## 3-Bag Collection System

### Action Required

#### ISSUE:

We have received reports of the bag coming in contact with the exhaust system of the engine.

#### CORRECTION:

Install muffler guard kit, part number 970336. Refer to attached Instruction Sheet for details.

#### PARTS INVOLVED:

970336 Kit, Muffler Guard

#### INVOLVED PRODUCTS:

970323	52" Bob-Cat Logo 3 bag spindle drive collection system
970324	52" No logo 3 bag spindle drive collection system
970325	61" Bob-Cat Logo 3 bag spindle drive collection system
970326	61" No logo 3 bag spindle drive collection system

#### WARRANTY:

You may claim up to 0.2 hours of labor and parts for units covered under this bulletin. Please file warranty using Service Bulletin Number **C-045-05** with one unit per claim. If you have any questions please contact the Jacobsen Product Support Team @ 800-848-1636 option 2,3,1.

### CustomerOne™ Product Support


This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE	<input checked="" type="checkbox"/>	WARRANTY	<input checked="" type="checkbox"/>	SALES	<input checked="" type="checkbox"/>	PARTS	<input checked="" type="checkbox"/>
---------	-------------------------------------	----------	-------------------------------------	-------	-------------------------------------	-------	-------------------------------------



**INTRODUCTION:** This instruction sheet covers the installation of the muffler guard plate to the rear frame of the ZT mowers.

1. Attach the muffler guard plate **1** between bumper arm **A**, plate **B** and bumper **C** as shown, using existing hardware. Tighten all fasteners at this time.



ITEM	PART NO.	DESCRIPTION	QTY
1	4140869	PLATE-MUFFLER GUARD 1	