

## **Parts Information Bulletin**

**Date: 5/02/2007**

**Product Type: Steiner 430**

**Bulletin No: JC-007-07**

**Action Required:** For informational purposes only.

**ISSUE:** Micro Switch. 31-038 replaced by 4162865 Due to NLA by original vendor.  
This requires minor modification to existing mounting bracket

**CORRECTION:** See following detailed explanation

**PARTS INVOLVED:** 31-038

**PRODUCTS INVOLVED:** Steiner Model 430

**WARRANTY:** This bulletin is for information purposes only.  
If you have any questions please contact Commercial Grounds Care, Inc.  
Customer Service Department @ 920-699-2000

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒

WARRANTY ☐

SALES ☐

PARTS ☒



# CGC

*Commercial Grounds Care, Inc.*

*One BOB-CAT Lane  
P.O. Box 469  
Johnson Creek, WI 53038-0469*

*Phone: 920.699.2000*

*Fax: 920.699.3683*

**Switch 31-038 REPLACED by 4162865 but  
REQUIRES modification to existing Bracket**

**Drill an additional 5/32" hole @ the dimensions  
shown below to accomodate new switch # 4162865**

