



One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038 U.S.A.
(920) 699 2000
Fax: (920) 699 6836

INFORMATION BULLETIN

430 Air Filter Change

Date: January 03, 2013

Bulletin No: JC-13-05

Product Type: STEINER 430 with Kubota engine

Customer Issue: Kubota made a change to their air filter assembly and the wrong components could be ordered.

Cause: Kubota has changed the air filter from a steel canister to a plastic canister. Models 75-70006A and 75-70008A can have either steel or plastic canisters.

Action required: When ordering parts for the air filters, the customer should know what they have installed on their unit (Steel or Plastic) and order the appropriate parts, according to the chart below.

Steel




Plastic





One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038 U.S.A.
(920) 699 2000
Fax: (920) 699 6836

Drawing number	Steel part number	Plastic part number
1 Assembly	13-15372-11016	4165658
2 Cap	13-15241-11160	4165658-02
3 Filter element	13-70000-11221	4165658-01



Products Involved: 430 water cooled tractors: 75-70006, 75-70006A, 75-70008, 75-70008A

Warranty: Warranty does not apply. This is an information bulletin to let you know how to ensure the customer receives the correct parts.

If you have any questions, please contact our Customer Service Department at 920-699-2000.

This bulletin is relevant to the departments checked below. Please circulate as appropriate.

SERVICE



WARRANTY



SALES



PARTS

