



One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038 U.S.A.
(920) 699 2000
Fax: (920) 699 6836

Information Bulletin

Date: September 11, 2017

Bulletin No: JC-17-11REV1

Product Type: QuickCat



Customer Issue: Unable to fit After-market catcher on QuickCat.

Cause: Specific serial range QuickCats have a discharge opening that some after-market catchers may not accommodate. (Consult after-market manufacturer's website for specific fitment information) **Note: BOB-CAT brand catchers are compatible with all QuickCat units.**

Action Required: Order Kit 970575 if fitting an after-market catcher to the below serial number units. List price \$40.00

Products Involved:

48" model 912480 serial 00406 – 00899
52" model 912520 serial 00631 – 01199
61" model 912610 serial 00070 - 00399

Summary of adapters for all QuickCat units that are fitting an after-market catcher:

Model	Serial Number	Kit(s) Req'd
912480	70 - 405	970540 & 970541
912480	406 - 899	970575
912480	900 and up	970558
912520	70 - 630	970434 & 970541
912520	631 -1199	970575
912520	1200 and up	970558
912610	70 - 399	970575
912610	400 and up	970558

Warranty: Not applicable

If you have any questions, please contact our Customer Service Department at 920-699-2000. This bulletin is relevant to the departments checked below. Please circulate as appropriate.

SERVICE WARRANTY SALES PARTS