



One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038 U.S.A.
(920) 699 2000
Fax: (920) 699 6836

Information Bulletin

Date: June 7, 2018

Bulletin No: JC-17-11REV2

Product Type: QuickCat™



Customer Issue: Unable to fit After-Market catcher on QuickCat.

Cause: Specific serial range QuickCats have discharge openings that are not compatible with after-market catchers.

Action Required: Order Kit(s) according to chart below.

Summary of adapters required for fitting an after-market catcher on QuickCat:

Model	Serial Number	Kit(s) Required
912480	70 - 405	970540 & 970541
912480	406 - 899	970540 & 970541 & 970575
912480	900 & Up	970558
912520	70 - 630	970434 & 970541
912520	631 - 1199	970434 & 970541 & 970575
912520	1200 & Up	970558
912610	70 - 399	970434 & 970541 & 970575
912610	400 & Up	970558

Products Involved: 912480, 912520, and 912610.

If you have any questions, please contact our Customer Service Department at 920-699-2000.

This bulletin is relevant to the departments checked below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☐ SALES ☒ PARTS ☒