



One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038 U.S.A.
(920) 699 2000
Fax: (920) 699 6836

Information Bulletin

Date: March 1, 2018

Bulletin No: JC-18-06

Product Type: Steiner tractor 75-75037xx (xx = represents any letter) with Briggs & Stratton 37HP EFI engine.

Customer Issue: Please see the attached letter from Briggs & Stratton. They have identified a potential concern for a failed regulator on the 20/50 amp charging system in their Briggs & Stratton 37HP EFI engines which can occur when the unit is not in use. The affected engines were incorporated in the Steiner tractors referred to above.

Action Required: **STOP SALE / STOP USING –** If you have Steiner tractor with one of the affected engines, please disconnect the battery immediately or you can trip the 150AMP breaker located on the rear of the Right-Hand fender; when pressed in this accomplishes the same thing as disconnecting the battery as advised in the Briggs & Stratton bulletin. Do not use the tractor until a service kit is installed (See Updating section below).

A: BATTERY DISCONNECT AND CIRCUIT BREAKER

The battery disconnect/circuit breaker switch controls power to the entire electrical system.

Pressing the red button trips the breaker and disables the electrical system, allowing electrical components to be serviced. To reset the battery disconnect/circuit breaker rotate the reset lever back into the horizontal and locked position.



Updating: Briggs & Stratton has created a service kit which simply requires installing a short fuse assembly which is installed into the wiring harness. For all authorized Briggs & Stratton dealers, you must work directly with Briggs for handling per your normal process.

If you are not an authorized Briggs & Stratton dealer, Briggs will be contacting you to make arrangements to have the engine updated.

Products Involved: Model number 75-75037, Serial numbers 75750370168 to 75750370191

Warranty: Covered through Briggs & Stratton distribution channel.

If you have any questions, please contact our Customer Service Department at 920-699-2000. This bulletin is relevant to the departments checked below. Please circulate as appropriate.

SERVICE



WARRANTY



SALES



PARTS

