



Bobcat/Bunton Service Bulletin

Product Type: Miscellaneous

Ref. No. N/A

Bulletin No: C-045-05

November 28, 2005

3-Bag Collection System

Action Required

ISSUE:

We have received reports of the bag coming in contact with the exhaust system of the engine.

CORRECTION:

Install muffler guard kit, part number 970336. Refer to attached Instruction Sheet for details.

PARTS INVOLVED:

970336 Kit, Muffler Guard

INVOLVED PRODUCTS:

970323	52" Bob-Cat Logo 3 bag spindle drive collection system
970324	52" No logo 3 bag spindle drive collection system
970325	61" Bob-Cat Logo 3 bag spindle drive collection system
970326	61" No logo 3 bag spindle drive collection system

WARRANTY:

You may claim up to 0.2 hours of labor and parts for units covered under this bulletin. Please file warranty using Service Bulletin Number **C-045-05** with one unit per claim. If you have any questions please contact the Jacobsen Product Support Team @ 800-848-1636 option 2,3,1.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE	<input checked="" type="checkbox"/>	WARRANTY	<input checked="" type="checkbox"/>	SALES	<input checked="" type="checkbox"/>	PARTS	<input checked="" type="checkbox"/>
---------	-------------------------------------	----------	-------------------------------------	-------	-------------------------------------	-------	-------------------------------------

