

PARTS BULLETIN

January 22, 2010

Bulletin No: JC-001-10

Product Type: SC101 Stump Cutter

Issue: Cutter bit description change (not part number)

Correction: When ordering cutters, refer to the drawing and part number – ignore "left" and "right" in the description of the parts book. This is due to confusion with what is considered "left" and "right".

Action Required: Put the following 2 pages in your parts book for future reference

Parts Involved: 79-054 and 79-055

Warranty: Does not apply

If you have any questions, please contact the Schiller Grounds Care, Inc. Customer Service Department at 920-699-2000.

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE


Х





PARTS			
Х			

MOW IT - BLOW IT - TRENCH IT - HAUL IT - DRILL IT - TILL IT - DO /



Ref #	Part Number	Qty	Description
1	79-055	10	Cutter
2	79-056	4	Cutter
3	79-054	10	Cutter
4	79-057	12	HOLDER-THREADED
5	79-058	12	HOLDER-COUNTERSUNK
6	99-20	24	BOLT, 5/8-18 X 1-3/4
7	55-PB22023	2	BEARING-PILLOW BLOCK
8	4136416.7	1	STUMP CUTTER ROTOR
9	83-SF23	1	BUSHING, SF X 1-7/16
10	64164-26	2	KEY-3/8x3/8x1-1/2 SQ
11	80-226	1	SHAFT-CUTTER
12	64123-24	4	BLT-HEX 1/2-13X2
13	64163-67	6	WASHER516X1X12GA
14	64006-05	10	LOCKWSHR-HELICAL 1/2
15	64025-09	6	HEX. NUT 1/2-13
16	83-3B46SD	2	PULLEY-3 GROOVE
17	42-398	2	TIGHTENER-BELT IDLER
18	D3032	1	BUSHING
19	83-SD23	1	BUSHING
20	81-B045	3	BELT-B45
21	64164-10	1	1/4X1/4X1-1/4 MACH KEY
22	83-SD20	1	BUSHING
23	87-175	1	GEARBOX
24	29-079	1	PIPE NIPPLE, 1/2 X 1.1/2
25	24-033	1	CAP-VENTED
26	90-0808	4	BOLT
27	83-BK60H	1	PULLEY
	81-A043	1	DRIVE BELT-A43
	81-B045	1	DRIVE BELT-B45
	81-A043	1	DRIVE BELT-A43
	81-B044	1	DRIVE BELT-B44
28	64164-11	1	KEY-3/16X3/16X1-1/4 SQ
	70-098	1	GEARBOX KIT
	D3032	1	BUSHING
	87-175	1	GEARBOX
	83-BK60H	1	PULLEY
	64164-11	1	KEY-3/16X3/16X1-1/4 SQ