



INFORMATION BULLETIN

January 22, 2010

Bulletin No: JC-002-10

Product Type: BOSS-VAC 52" and 61", 3 Bag Collection System Belt Cover

Issue: The F model ProCat, Predator Pro, Torpedo, and Missile model zero turn riders are designed to allow for a higher height of cut than the previous A, B, C, D, and E units. The field has reported interference between the collection system belt cover, rear rocker arm, and cradle that won't allow the deck to be set in the transport position. Since receiving the field reports we've redesigned the collection system belt cover so it will not interfere on F models.

Action Required: If a customer reports this situation to you, simply check for interference between the existing cover, rear rocker arm, and cradle. Should this be the problem, call us and we will ship the correct belt cover to the dealer. **Note:** These items can only be ordered by contacting the Customer Service department at 920-699-2000.

Parts Involved: 4137460 Belt Cover 52" or 4137079 Belt Cover 61"

Products Involved: BOSS-VAC Collection System 970323, 970324, 970325, 970326, and ProCat, Predator Pro, Torpedo, and Missile F model zero turn riding units.

Warranty: Does not apply

If you have any questions, please contact the Schiller Grounds Care, Inc. Customer Service Department at 920-699-2000.

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE

☒

WARRANTY

☐

SALES

☒

PARTS

☒

*Schiller Grounds Care, Inc.
One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038*

Phone: 920.699.2000

Fax: 920.699.6836