



One BOB-CAT Lane, P.O. Box 469  
Johnson Creek, WI 53038 U.S.A.  
(920) 699 2000  
Fax: (920) 699 6836

## SERVICE BULLETIN

May 4, 2010

Bulletin No: JC-003-10

### **Dual Wheel Lug Bolts**

**Product Type:** Dual Wheel Kit for STEINER Tractors

**Issue:** Lug bolts are too long in the dual wheel kits for the current tractors in production.

**Correction:** Shorter bolts have been added to the current inventory at the factory (these kits will have both short and long bolts in them). All future builds will **JUST** have the shorter bolts in the dual kits.

**Action Required:** You will need the shorter bolts when assembling a dual kit onto a Steiner tractor that has the new style hub. The old style Hub will need the longer bolts. All other assembly directions should be followed as they are in the instructions. Field Trax tires may still need the extra washer installed, so the tires do not rub each other.

**Parts Involved:** (see pictures, provided at the end of bulletin)

- The old hub - long bolt, part# 99-F37 changes to 64123-277 and is ½-20 x 3"
- The new hub - shorter bolts are 64123-276 and are ½-20 x 2-1/4"

**Products Involved:**

- 75-70480 Bar Tire Kit
- 75-70482 Peanut Turf Tire Kit
- 970306 Field Trax Tire Kit

**Warranty:** No warranty applies. If you have duals in stock, order the short bolts as needed and retain the long bolts in inventory to use as replacement parts for old dual kits.

If you have any questions, please contact the Schiller Grounds Care, Inc. Customer Service Department at 920-699-2000.

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE



WARRANTY



SALES



PARTS





One BOB-CAT Lane, P.O. Box 469  
Johnson Creek, WI 53038 U.S.A.  
(920) 699 2000  
Fax: (920) 699 6836

New Style Hub -  
Requires shorter  
lug bolts  
64123-276



Old Style Hub -  
Requires longer  
lug bolts  
64123-277



MOW IT ► BLOW IT ► TRENCH IT ► HAUL IT ► DRILL IT ► TILL IT ► **DO IT.**

**DO IT.**