



One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038 U.S.A.
(920) 699 2000
Fax: (920) 699 6836

Service Bulletin

June 22, 2010

Bulletin No: JC-012-10

Propane Catcher Inlet Boot

Issue: Different Grass Catcher Inlet Boot is required on Propane units.

Details: Due to the size of the propane fuel tanks, a different inlet boot (4165360.7) is required for the 3 bag catcher. This new boot will also work on all other units. Therefore, we will begin including this boot in all catchers shipped from the factory.

Action Required: If you sell a propane unit that is having a 3 bag catcher installed and the catcher is old stock, you will need to call us with the serial number. At that point, we will send a boot out at no charge to allow the catcher to be fitted to the propane unit.

Products Involved: Old style boot 4139394 supersedes to new style boot 4165360.7

Warranty: Warranty does not apply.

If you have any questions, please contact the Schiller Grounds Care, Inc. Customer Service Department at 920-699-2000.

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE

☒

WARRANTY

☐

SALES

☒

PARTS

☐

Exactly What You Need