


INFORMATION BULLETIN

November 23, 2009 Original Date: June 24, 2009

Bulletin No: JC-015-09

PRODUCTS INVOLVED: STEINER 230 - Serial Numbers; 3001 - 4199

ISSUE: 31-053 F & R Neutral switch is obsolete. Replace it with kit 4164127



NEW SWITCH AND BRACKET INSTALLED.

DISCARD OLD SWITCH BRACKET

Switch must be adjusted to work properly by sliding the bracket in the slots of the holders.

WARRANTY: WARRANTY NOT APPLICABLE – Information Only

If you have any questions please contact the Schiller Grounds Care, Inc. Customer Service Department at 920-699-2000.

This bulletin is relevant to the departments shown below. Please circulate as appropriate.



MOW IT - BLOW IT - TRENCH IT - HAUL IT - DRILL IT - TILL IT - DO /