

INFORMATION BULLETIN

Date: 11/12/2007

Product Type: RYAN LAWNAIRE IV & V

Bulletin No: JC-024-07

HONDA ENGINE SPEED

ISSUE: It has been brought to our attention that the Lawnaire IV and V's may have the maximum engine speed set too high. This will manifest itself in complaints from customers of excessive ground speed and operator fatigue as well as complaints of frame cracks.

CORRECTION: Check governor speed is set to a maximum of **3200 RPM's**

ACTION REQUIRED: This does **NOT** affect all units but it is a simple thing to check and takes minimal effort to rectify (simply turn the high speed limiting screw).

PARTS INVOLVED: None

PRODUCTS INVOLVED: All Lawnaire IV & V's with HONDA engines

WARRANTY: This is an Informational bulletin, Warranty does not apply.

If you have any questions please contact Commercial Grounds Care, Inc.
Customer Service Department @ 920-699-2000

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒

WARRANTY ☐

SALES ☒

PARTS ☐

