



One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038 U.S.A.
(920) 699 2000
Fax: (920) 699 6836

Information Bulletin

Date: January 28, 2014

Bulletin No: JC-13-15

Product Type: BOB-CAT Walk-Behind Gear Drive Mowers

Customer Issue: Ordering the correct replacement bearing for rear wheel drive assemblies, 4162837 and 4162836.

Cause: Two different vendors have supplied us the same wheel part number over the course of several years. Though each wheel assembly looks the same, the bearing outside diameter is slightly different.

Action Required: When ordering service bearings for the wheel assemblies mentioned above, please note the two different sizes listed below. Please inspect for the proper bearing OD prior to ordering.

1. Bearing 2721432-3 = 2.0" O.D. (marked 1641-2RS)
2. Bearing 4128899-03 = 2.047" O.D. (marked 6205-2RS-1 NR SP)

Products Involved: Models 632006, 932006, 932007 and 932007G.

Warranty: Warranty does not apply. This is an information bulletin to let you know how to select the proper bearing should you encounter a fit issue.

If you have any questions, please contact our Customer Service Department at 920-699-2000.

This bulletin is relevant to the departments checked below. Please circulate as appropriate.

SERVICE

☒

WARRANTY

☐

SALES

☐

PARTS

☒