

Jacobsen Service Bulletin

Product Type: UM4280 Utilimax

Ref. No. 001

Bulletin No: C-015-04

June 21, 2004

Steering Cylinder Mount

Action Required

ISSUE:

Replacement of the steer cylinder mount.

CORRECTION:

We will be sending one kit 970310 per unit, to the selling dealer. Kit needs to be installed before December 21st, 2004 on the provided serial numbered units.

AFFECTED SERIAL NUMBERS:

All serial numbers for the following models:

73-70134 Serial numbers 1334 and 73701340071

73-70136 Serial numbers Y1343 up and including Y1351

73-70136 Serial numbers 73701360101 up to and including 73701360105 and 73701360071

WARRANTY:

Please file warranty claims, using **Factory Approval Number C-015-04**. You may claim up to one-hour labor for repair.

Retailed units registered will be eligible for \$50.00 administration/pick and delivery charge.

If you have any questions please contact Jacobsen Service Department @ 800-848-1636 select option 3,2.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE

☒

WARRANTY

☒

SALES

☐

PARTS

☐