

# Jacobsen Product Information Bulletin

Product Type: **Z-FASTCAT ES**

Ref. No.

Bulletin No: **C-153-03**

October 2003

## Transmission Maintenance

### Product Information

#### ISSUE:

Correction to manual 4125723 and 4125723 Rev. A and 4125723 Rev. B. **We DO NOT require you to change the transmission hydraulic oil after 5 hours of use as stated in the Maintenance Record section of the manual.**

#### CORRECTION:

On the page labeled Maintenance Record of the Jacobsen Operation, Safety and Maintenance Manual, you need to change the NOTE on the bottom of the page to read as follows: **After first 5 hours of operation replace engine oil and filter.** This is for Z-Fastcat ES model only.

#### INVOLVED PRODUCTS:

All serial numbers for the following models:  
742280, 742281, 742282

#### WARRANTY:

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Johnson Creek product support team at 1-800-848-1636 option 2,2.

## CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☐ PARTS ☒