

Deck Chain Guides

Models Affected: 942301

Issue

We have added Deck Chain Guides **2722267.7** to assist in preventing the lift chains from coming off.

Correction

The Deck Chain Guides **2722267.7** may be added to prior machines should they be experiencing problems with the chains coming off. You will need to drill 2) 5/16" holes in front of the front deck lift chains and install the following parts:

- 2) **2722267.7** Guides
- 2) **64123-54** Bolts
- 2) **64163-55** Nuts.

Effective Serial Number

All 942301 machines with serial numbers up to and including 94230100127.

Warranty

This is an informational bulletin only. Warranty does not apply.

Parts Involved

2722267.7 Guides.
64123-54 Bolts.
64163-55 Nuts.

If you have any questions about this bulletin, please contact the Textron Golf, Turf And Specialty Products Service Department at 920-699-5890.