

Product Type: BZT2000 Ref. No. 024

Service Bulletin J613

Mandatory Update

March 2003

Spring Washer 64209-03

Models Affected:

642211(A), 642220(A), 642221(A)
644222(A), 642223(A), 642230(A), 642231(A), 642233(A)

Issue

Blade and Spindle mounting washers **Spring Washer 64209-03** are not properly harden.

Correction

Sold units

At the next blade sharpen please replace the present Spring Washers with the new **Spring Washers 64209-03**.

Non-sold units

Please replace present Spring Washers with the new **Spring Washers 64209-03** at set-up.

Torque the blade and pulley bolts to 70 ft/lbs.

Effective Serial Number

All 642211(A) units with serial numbers 64221103117 up to and including 03133, 03338 up to and including 64221103349.

All 642220(A) units with serial numbers 64222000185, 00186, 00407 up to and including 64221100420.

All 642221(A) units with serial numbers 64222103111 up to and including 03120, 03330 up to and including 64222103355.

All 642222(A) units with serial numbers 64222203003 up to and including 03010, 03311 up to and including 64222203316.

All 642223(A) units with serial numbers 64222300369 up to and including 00377, 00578, 00579, 00580, 03001 up to and including 64222303005.

All 642230(A) units with serial numbers 64223000162, 00163, and 64223003001.

All 642231(A) units with serial numbers 64223100359.

All 642233(A) units with serial numbers 64223300532, 00533, 00534, 00535, 00736 up to and including 00755, and 64223303001.

Warranty

Parts are being sent to you at no charge. You may claim the up to .6 labor per unit. Please file warranty in the normal matter.

This update must be completed within 60 days.

Parts Involved

64209-03 Spring Washer

If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty Products Service Department at 920-699-5890.