

Bunton

Product Type: BZT1000

Ref. No. 015

Service Bulletin J589

April 2002

Maintenance Free Caster Wheel Bearings

Models Affected: 654204, 654803, 654804

Issue

We have released Maintenance Free Caster Wheel Bearings for the BZT1000's.

Correction

When ordering a 2720646 Wheel Assemble you will receive 1) 2722681 Wheel Assemble, 1) 272230-04 Spanner, and 2) 2722591 Spacers.
When ordering a 38508 Hub you will receive 1) 2722680 Hub, 1) 2722230-04 Spanner, and 2) 2722591 Spacers.

Effective Serial Number

All 654204 Cutterdecks. All 654803 Cutterdecks. All 654804 Cutterdecks.

Warranty

This is an informational bulletin only.

Parts Involved

2720646 - Wheel Assemble 2722681 - Wheel Assemble 38508 - Hub 2722680 - Hub 2722230-04 - Spanner 2722591 - Spacer

If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty Products Service Department at 920-699-5890.