

Product Type: BZT1000

Bunton

Service Bulletin J529

Ref. No. 009

March 2001

Blower Assembly Kit

Models Affected: 642105

Issue

We have released a Blower Assembly Kit **970206** for the BZT1000 collections units. The assembly is made of an abrasive resistance steel for longer life.

Correction

When replacing the Fan or Blower Housing you will receive a complete Blower Assembly. The Blower Assembly will come completely assembled.

Effective Serial Number

All 642105 units.

Warranty

You may claim up to 1.5 hours plus the 970206 Blower Assembly Kit for units within the normal warranty period. For units outside the normal warranty period please contact the Johnson Creek Service Department. Please file warranty in the normal way with one unit per claim.

Parts Involved

970206 Blower Assembly Kit. 2226006.7 Wldmt-Blower. 2226007.7 Wldmt-Fan. 2721588.7 Ring-Blower Wear.

If you have any questions about this bulletin, please contact the Textron Golf, Turf And Specialty Products Service Department at 920-699-5890.