



Product Type: ZT331 Ref. No. 002

Bob-Cat

Service Bulletin J454_{Rev01}

May 2000

New Control Arm Dampner

Models Affected:
942300

Issue

A new stiffer steering Control Arm Dampner has been released for the ZT331.

Correction

When ordering a new Dampner, please order part number **2721172**. The new dampner will have a white spot on the end to identify it.

Please note that the old Dampner will not automatically supercede to the new Dampner.

Effective Serial Number

All 942300 power units.

Warranty

This bulletin is for informational purposes only. Warranty does not apply.

Parts Involved

2721172 Control Dampner.

If you have any questions about this bulletin, please contact the Textron Turf Care And Specialty products Service Department at 920-699-5890.