





Ryan Information Bulletin

Product Type: Lawnaire 28 Ref. No. N/A Bulletin No: C-042-04

November 1, 2004

Tine Arm Welds


Action Required

ISSUE:

It has come to our attention that part number 547509.7 might be welded incorrectly.

CORRECTION:

Need to inspect part number 547509.7 to see that the tine arm is welded as shown. If not you will need to have the tine arm welded on both sides at the "x".



PARTS INVOLVED:

547509.7

INVOLVED PRODUCTS:

544874D: Serial numbers 54487400070 up and including 54487400426

WARRANTY:

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Jacobsen Customer Service Team at 1-800-848-1636 option 2,2.

CustomerOne[™] Product Support

This bulleti	n is r	elevant to the depa	artme	ents shown be	elow.	Please circ	ulate	as appropriate.
SERVICE	X	WARRANTY	X	SALES		PARTS	X	

