



Bulletin No: SB2004-08

Category: STEINER

Section: N/A

Index Ref: N/A

Machine/s: Model 230

Pages: 1

Date: September 10, 2004

Type: Product Information

TO: All Steiner Dealers

SUBJECT: Model 230 drive axle kit 970311

ISSUE:

Change to the drive axle shaft size.

CORRECTION:

When ordering part number 51-024 you will receive kit 970311. This kit will include all necessary parts to replace axles on both sides of the unit.

AFFECTED SERIAL NUMBERS:

Model 75-70256 prior to serial number 75702560134

Model 75-70258 prior to serial number 75702580110

Model 75-70265 prior to serial number 75702650143

WARRANTY:

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Jacobsen product support team at 1-800-848-1636 option 3,2.

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE

☒

WARRANTY

☐

SALES

☐

PARTS

☒