





Bulletin No: SB2004-11 Category: STEINER Section: N/A Index Ref: N/A Machine/s: Model 230 Pages: 1 Date: November 1, 2004

Type: Product Information

TO: All Steiner Dealers

SUBJECT: Kohler muffler

ISSUE:

Muffler replacement on Kohler engine models.

CORRECTION:

When replacing muffler part number 13-071 you should order kit 970321. This kit will include the parts and instructions needed to replace the muffler.

AFFECTED SERIAL NUMBERS:

All serial numbers for the following models: Model 75-70256 serial number prior to 75702560131

WARRANTY:

This bulletin is for information purposes only. Warranty does not apply. If you have any questions please contact the Jacobsen Product Support Team at 1-800-848-1636 option 3,2.

CustomerOne[™] Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.



