



Ryan Service Bulletin

Product Type: 36" TOW Lawnaire

Ref. No. N/A

Bulletin No: C-025-06

July 10, 2006

544860 Tire Assembly

Action Required

ISSUE:

Tire may rub Yoke.

CORRECTION:

Change tire assembly with hardware.

53-186 Wheel/Tire (Item 42)


50-062 Spacer (Item 10)

64123-130 Bolt (Item 38)

64163-61 Washer (Item 61)

64163-16 Washer (Item 43)

64229-03 Lock nut (Item 41)



INVOLVED PRODUCTS:

544860 - 36" TOW Lawnaire with serial numbers below 54486000305.

WARRANTY:

You may claim up to 20 minutes for units in the warranty period. When filing warranty claim, please use number **C-025-06** in the "Campaign Number" field with one unit per claim. If you have any questions please contact the Jacobsen Product Support Team at 1-800-848-1636 option 2,3,1.

Updates must be completed by October 1st, 2006. No warranty claims will be processed after November 1st, 2006

CustomerOne™ Product Support

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE ☒ WARRANTY ☒ SALES ☒ PARTS ☒

