



One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038 U.S.A.
(920) 699 2000
Fax: (920) 699 6836

Information Bulletin

Date: September 7, 2017

Bulletin No: JC-17-11

Product Type: QuickCat



Customer Issue: Unable to fit after-market catcher on QuickCat.

Cause: Specific serial range QuickCats have a discharge opening that some after-market catchers may not accommodate. (Consult after-market manufacturer's website for specific fitment information) **Note: BOB-CAT brand catchers are compatible with all QuickCat units.**

Action Required: Order Kit #970575 of fitting an after-market catcher to the below serial numbered units.

Products Involved:

48" model 912480 serial 00406-00899

52" model 912520 serial 00631-01199

61" model 912610 serial 00070-00399

Warranty: Not applicable

If you have any questions, please contact our Customer Service Department at 920-699-2000.

This bulletin is relevant to the departments checked below. Please circulate as appropriate.

SERVICE
☒

WARRANTY
☐

SALES
☒

PARTS
☒