



SERVICE BULLETIN

May 1, 2009

Bulletin No: JC-010-09

Subject: Pump Idler Spring – Running Change

Product Type: All BOB-CAT FastCat & Bunton Rocket Models

ISSUE: The pump idler spring has been revised on the FastCat and Rocket models. This change has been incorporated across all FastCat & Rocket models. Manufacturing has initiated a running change to production for the Pump Idler Spring # 38219 to part number 4164128.

ACTION REQUIRED: If any FastCat or Rocket comes in for replacement of the idler spring either in or out of warranty, use part number 4164128.

PARTS INVOLVED: Part # 38219; use part 4164128 for this application. **THIS IS NOT A SUPERSEDE** as the # 38219 is still used in other applications.

PRODUCTS INVOLVED: All Bunton models starting 64229XX, 64231XX, and 642404F
All BOB-CAT models starting 94229XX, 94231XX, and 942404F

WARRANTY: Warranty only applies if the unit fails under warranty. If failure occurs in the warranty period, file a claim as you normally would for any warranty job. This is not a rework.

Production will begin installing the 4164128 spring starting at the serial numbers listed below:

Bunton Models

642291F	Rocket – 17 HP Kaw w/36 SD	64229102100
642295F	ZT Rocket – 19 HP Kaw w/48 SD	64229502130
642296F	ZT Rocket – 19 HP Kaw w/52 SD	64229602130
642311F	ZT Rocket CZ – 22 HP B&S w/42 SD	64231100110
642313F	ZT Rocket CZ – 26 HP B&S W/52 SD	64231300111
642404F	ZT Rocket - 23 HP B&S w/61 SD	64240400100

*Schiller Grounds Care, Inc.
One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038*

Phone: 920.699.2000

Fax: 920.699.6836



BOB-CAT Models

642291F	FastCat Pro – 17 HP Kaw w/36 SD	94229102106
642295F	FastCat Pro – 19 HP Kaw w/48 SD	64229502866
942296F	FastCat Pro – 19 HP Kaw w/52 SD	94229602397
942311F	FastCat – 22 HP w/42 SD	94231100156
942313F	FastCat – 26 HP w/52 SD	94231300209
942404F	FastCat Pro – 23 HP B&S w/61 SD	94240400098

This bulletin is relevant to the departments shown below. Please circulate as appropriate.

SERVICE

☒

WARRANTY

☒

SALES

☐

PARTS

☒

If you have any questions please contact Schiller Grounds Care, Inc. Customer Service Department at 920-699-2000.

*Schiller Grounds Care, Inc.
One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038*

Phone: 920.699.2000

Fax: 920.699.6836