

One BOB-CAT Lane, P.O. Box 469 Johnson Creek, WI 53038 U.S.A. (920) 699 2000

Fax: (920) 699 6836

INFORMATION BULLETIN

Relocate fuel filter for ease of access

Date: January 03, 2013

Bulletin No: JC-13-02

Product Type: STEINER 440 Tractor equipped a Kubota engine

Customer Issue: Poor accessibility to the fuel filter for service

Cause: Due to the fuel filter being located under the foot plate, it is not easily serviced.

Action required: If customer requests improved accessibility, relocate the fuel filter behind the foot plate.

Use caution; there will be small amounts of fuel draining out of the fuel hoses when disconnecting them.

- 1. Order a new 5/16" fuel hose. 4162978-001
- 2. Remove the foot plate to gain access to the fuel filter.
- 3. Locate and clamp the fuel line coming from the tank with a fuel line clamp.
- 4. Remove the 3" long line from the fuel pump and filter and discard it. Save the clamps for use when reassembling it.
- 5. Cut a 10" piece from the new hose; and assemble it onto the filter where the 3" hose was.
- 6. Remove the filter from the fuel hose coming from the tank: cut 7" off and discard it. Save the clamp for use when reassembling it.
- 7. Reassemble the filter back on the shortened hose coming from the tank.
- 8. Assemble the open end of the 10" hose to the fuel pump.
- 9. Remove the fuel hose clamp and start the engine and let it bleed the air out of the fuel hoses.
- 10. Check for leaks and put the foot plate back in place.

Products Involved: 75-72010 440 Kubota diesels and 75-72011 440 Kubota gas tractors.

Warranty: Warranty does not apply. This is an information bulletin. In future production we are changing the location of the fuel filter and the hose lengths will change. It is a good idea to do this update if a cab is installed on the tractor.

If you have any questions, please contact our Customer Service Department at 920-699-2000.

This bulletin is relevant to the departments checked below. Please circulate as appropriate.

SERVICE	WARRANTY	SALES	PART
X			X



One BOB-CAT Lane, P.O. Box 469 Johnson Creek, WI 53038 U.S.A. (920) 699 2000

Fax: (920) 699 6836

