





Informational Bulletin

Product Type: CGC Ref. No. N/A Bulletin No: C-017-06

May 1, 2006

Grass Catcher

Product Information

ISSUE:

Bag Catcher flexible hose interfering with tire in some cases.

CORRECTION:

Relocate the hose clamp mounting bolt center to 3" from hose end of chute. See Drawing.

PARTS INVOLVED:


4137086 Transition Chute 4137066 Hose

INVOLVED PRODUCTS:

970324 3 Bag Catcher 970326 3 Bag Catcher

WARRANTY:

This bulletin is for information warranty does not apply.



CustomerOne[™] Product Support

This bulleti	n is re	elevant to the depa	artme	ents shown b	elow.	Please circu	ulate a	as appropriate
SERVICE	X	WARRANTY	X	SALES	X	PARTS		

