One BOB-CAT Lane, P.O. Box 469 Johnson Creek, WI 53038 U.S.A. (920) 699 2000

Fax: (920) 699 6836

Service Bulletin

Date: 4/30/2015


Bulletin No: JC-15-09

Product Type: Ren-O-Thin

Customer Issue: The drive belt could possibly walk off of the idler pulley when transitioning between engagement and disengagement of the drive belt.

Cause: The variation of individual component tolerances could contribute to this situation.

 The effects of these variations are eliminated by using an idler pulley with side lips to retain the belt.



Action Required: Units in the below affected serial range, need a pulley 2228016 with washer 64163-31 installed in place of existing pulley (548942).

Remove belt cover. Remove pulley. Install washer between pulley and idler arm.

Products Involved: Model	Serial number
> 554870	< 00104
> 554871	< 00173
> 554872	< 00109
> 554873	< 00110
> 554874	< 00106
> 554875	< 00112



One BOB-CAT Lane, P.O. Box 469 Johnson Creek, WI 53038 U.S.A. (920) 699 2000

Fax: (920) 699 6836

See the following list for exceptions.

Exceptions:	the serial num	bers listed bel	low were rewo	rked at the factory
-------------	----------------	-----------------	---------------	---------------------

- > **554870******: 00071, 00100, 00101, 00102, 00103
- > **554871******: 00137, 00138, 00141, 00143, 00144, 00145, 00146, 00147, 00149, 00168, 00169, 00172
- > **554872******: 00070, 00071, 00100, 00101, 00102, 00103, 00104, 00105, 00106, 00108,
- > **554873******: 00100, 00101, 00102, 00106, 00107, 00108
- **554874******: 00070, 00071, 00100, 00101, 00102, 00103, 00104, 00105
- > **554875******: 00070, 00071, 00103, 00104, 00105, 00108, 00109, 00110, 00111

Warranty: You may claim up to .25 hour of labor and parts for units covered under this bulletin. Please file warranty using Service Bulletin Number JC-15-09 with one unit per claim.

If you have any questions, please contact our Customer Service Department at 920-699-2000.

This bulletin is re	elevant to the departme	nts checked below.	Please circulate	as appropriate.
SERVICE	WARRANTY	SALES	PARTS	
X	X	X		